

Changes to SATO Printer Drivers - Version 4.1.06

- Memory modules correction for Sato MB(SBPL) printers to 2 memory slots
- Fixed issue where printed documents sometimes get stuck in printer spooler
- Fixed Windows Explorer crash on Windows NT4 when selecting prefix/suffix type for Command fonts
- Fixed Barcode fonts where sometimes it produces the wrong contents (Valid for CODE128 barcodes)
- Fixed problems with internal date and time pictures in 64-bit drivers
- Fixed incorrect printer settings on Windows 9x for certain printers drivers
- S-84 printer drivers now use a different set of SBPL speed command
- When adding a port monitor, "Printer Install Wizard" shows a dialog for only certain specific printer models
- Fixed problem with RFID label data not being sent to the printer on Windows 9x
- Status monitor update: When bidirectional communication with printer is disabled, printer will not appear in the list box, Status Monitor updated to work with 64-bit drivers
- Solved issues with MB200i printer status reporting
- All printers that support RFID GEN2 commands now have the feature enabled by default
- New printer drivers were added to the SI_Enh and SI_Port driver distribution packages (CT408i, CT412i, CT424i, S-8408, S-8412, S-8424, MB400i)